|| Hare Krishna ||



Chartered Engineer (Civil), Structural Consultant & Valuer B. Tech & M. Tech in Civil Engineering, MIE (M-1562185). FIV (F-25129), Approved Valuer of I.O.V., Structural Engineer Factory Act Engineer, Fact Act Maps & Other Licensing Work & Approved Valuer of Govt. of India

Office :# 1192, Sector-9A, Urbarr Estate, Gurugram (HR) 122001 Contact No.: 9313219882, Landline No.: 0124-4380921 E-mail: rk.singhpappus@gmail.com

Ref. No. Sto Cest 2020/12/18



Date: 18/12/2020

CERTIFICATE OF STABILITY AND SAFETY OF THE SCHOOL

The structure design of school building has been checked and found to be in order. The design is in accordance with the provisions of the National Building Code and the relevant Bureau of India Standard Codes (with latest amendments) including Bureau standard codes for structures resistant to earthquakes. The local soil condition, its load bearing capacity and the underground water table etc. have been kept in view while designing the same.

DESCRIPTION OF SCHOOL BUILDING

Name of School	MEENAKSHI PUBLIC SCHOOL
Name of Society	
Location of School Building	Meenakshi Foundation
	Sector 10A, Gurugram 122001 (HR)
Examined Portion	Block 1, 2, 3 & 4
General type of construction	RCC Footing, RCC Columns, Slabs, Brick work with Cement Mortar 1:6 both side plasters flooring and painting.
Name of Secretary	Mr. Mohit Sachdeva
Total plot area	
	5.25 Acre
Year of constructions	Block 1, 2, 3, & 4 in year 1991, 2003, 2007 & 2012
ate of Issue	18.12.2020
ull name of signatory	Er. R.K. Singh
ualification	B.Tech/M.Tech (Structure)/ Chartered Engineer

Ray Kumen CHARTERED ENGINEER (C ENG) RAJKUMAR SINGH Member of Institution of Engineers (India) M-1562185 # 1192/9A, U.E. Gurgaon (Hr.) Mob.: 9313219882, 0124-4380921

Meenakshi Public School Sector - 10A, Gurgaon

